

SWA EAS1 disable all FDIR monitors  
File: IA-FCP-123.xls  
Author: n/a



**Procedure Summary**

**Objectives**

SWA disable all EAS1 FDIR monitors

**Summary of Constraints**

n/a

**Spacecraft Configuration**

**Start of Procedure**

Type Pre-condition Here

**End of Procedure**

Type Post-condition Here

**Reference File(s)**

**Input Command Sequences**

**Output Command Sequences**

AIAF123A

**Referenced Displays**

ANDs GRDs SLDs


**Configuration Control Information**

DATE	FOP ISSUE	VERSION	MODIFICATION DESCRIPTION	AUTHOR	SPR REF
------	-----------	---------	--------------------------	--------	---------

SWA EAS1 disable all FDIR monitors  
File: IA-FCP-123.xls  
Author: n/a



## Procedure Flowchart Overview



SWA EAS1 disable all FDIR monitors File: IA-FCP-123.xls Author: n/a	 
---	--

Step	Label/Time	Activity/Remarks/Branch	CK	Display
<b>Beginning of Procedure</b>				
Beginning of Sequence				
<b>AIAF123A</b>		<b>SWA EAS1 DisAllFdir</b> SeqFlags [ Crit/Plan/Stdalone/Sched ] : NSYN Forced Subschedule : SWA (109) TimeTag type : B		
1		<b>Step 1</b>		
		Disable EAS1 FDIR		
	+00.00.00	Send SWA_TC_PARS_MON_DIS ZIA58064 SWA_TC_PARS_MON_DIS TC Control Flags: GBM IL DSE --Y NC --- Command Parameters : PIA60452 NUM_OF_MON_ID = 12 <dec> PIA60449 MON_ID = EAS1SPWHB_MI <hex> PIA60449 MON_ID = E1_3V3_MI <hex> PIA60449 MON_ID = E1_1V5_MI <hex> PIA60449 MON_ID = E1OPTMPMON <hex> PIA60449 MON_ID = E1HVOUTVMON <hex> PIA60449 MON_ID = E1MCPVMON <hex> PIA60449 MON_ID = E1GRIDVMON <hex> PIA60449 MON_ID = E110VAPOSVMON <hex>		
		PIA60449 MON_ID = E128VPOSVMON <hex> PIA60449 MON_ID = E1HVGENTHERMON <hex> PIA60449 MON_ID = E1HVMODTHERMON <hex> PIA60449 MON_ID = EAS1MISSACK_MI <hex>		
End of Sequence				
<b>AIAF123A</b>				
<b>End of Procedure</b>				